

Sub Jan 23, 2017

Work Order ID 154706

154706

Page 1

Monday, December 19, 2016 4:00:11 PM

Item ID: D4635-044 Accept *N900040100* Setup Start *NS1*
 Revision ID: Stop *NS2*
 Item Name: Aft Ceiling Panel Assembly, RH
 Start Date: 1/6/2017 Start Qty: 1.00 *1* Cust Item ID:
 Required Date: 1/19/2017 Req'd Qty: 1.00 *1* Customer:
 Reference:

Approvals: Process Plan: DAS Date: DEC 20 2016 Tooling: Date: Run Start *NR1*
 QC: 21 Date: SPC (Y/N): Date: Stop *NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr								
D4635	F								
100		0.00							
100									
HandThermo	Memo	0.00							
Hand Finishing Thermoforming	Pick Kit								
110		0.00							
110									
Small Fab	Memo	0.16							
Small Fab	1- Assemble as per Dwg D4635-044								
	2-Install speaker								
	3- Install Air valve								
	4-Install Wiring Harness								
	5-Install wiring harness								

DAS JAN 12 2017

6
9.89

SMB
17/1/23

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																													
Date :		Step #:		QTY Effective :				MRB (QSI042) Approval																																																									
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval																																																									
Root Cause		FAULT CATEGORY																																																															
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER :			
Misidentified ☐	Past Due ☐																																																																

Work Order ID 154706

Monday, December 19, 2016 4:00:11 PM

154706

Page 2

Item ID: D4635-044 Accept ***N900040100*** Setup Start ***NS1***
Revision ID: Stop ***NS2***
Item Name: Aft Ceiling Panel Assembly, RH
Start Date: 1/6/2017 Start Qty: 1.00 ***1*** Cust Item ID:
Required Date: 1/19/2017 Req'd Qty: 1.00 ***1*** Customer:
Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____ Run Start ***NR1***
QC: _____ Date: _____ SPC (Y/N): _____ Date: _____ Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
120	QC5- Inspect part completeness to step on W/O	0.00							DAS 9 9-89
120									
QC	Memo	0.00							
Quality Control									
130	Identify as per dwg & Stock Location: <u>pk</u>	0.00							DAS 6 9-89 JAN 25 2017
130									
Packaging	Memo	0.00							
Packaging									
140	QC21- Final Inspection - Work Order Release	0.00							DAS 21 9-89 JAN 26 2017
140									
QC	Memo	0.02							
Quality Control									

JAN 25 2017

DAS
21
9-89

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐																																																											
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval																																																							
Description Work Order Deviation				Disposition				Completed By Lead hand / Supervisor Approval Verification QC / QA Coordinator Approval																																																							
Root Cause		FAULT CATEGORY																																																													
Environment ☐	No Re-verification ☐	Pressure/Forced ☐	Temperature/Cure ☐	Power Loss/Surge ☐	Positioned Wrong ☐	Design ☐	Operator ☐	Bending ☐	Set-up ☐	Folio/Program ☐	Outside Dimensions ☐	Doc/Data ☐	Offset/Setup ☐	Centre Not Concentric ☐	BOM/Route ☐	Grain ☐	Over/Under tolerance ☐	Equip/Tooling ☐	Supplier ☐	Cracks ☐	Broken/Damage/Defect ☐	Weld ☐	Part Incorrect ☐	Handling/Pre ☐	Training ☐	Crimp/Kink/Ripple/Wave ☐	Inspection Incomplete/Unqualified ☐	Wrong Stock Pulled ☐	Part Lost/Missing ☐	Material ☐	Use for Testing ☐	Cuffs ☐	Contamination ☐	Out of Sequence ☐	Part Moved ☐	Internal Transport ☐	Poor Information ☐	Crushing ☐	Countersink ☐	Off-set ☐	Drawing ☐	Tribal Knowledge ☐	Rushing ☐	Heat Treat ☐	Cut Too Short ☐	Mislabeled ☐	Finish ☐	LOA ☐	Product Improvement ☐	Wave/Twist in Tube ☐	Instructions Incomplete/Unclear ☐	Fit/Function ☐	Misread ☐	Substation ☐	Process Improvement ☐	Marks/Chatter ☐	Drill Holes ☐	Misaligned/off center ☐	Turning Sequence ☐	Past Expiry Date ☐	Manufacturing Process ☐	OTHER :	
Misidentified ☐	Past Due ☐																																																														

Picklist Print

Monday, December 19, 2016 4:00:14 PM

Page 1

Work Order ID: 154706

154706

Parent Item: D4635-044

D4635-044

Parent Item Name: Aft Ceiling Panel Assembly, RH

Start Date: 1/6/2017

Required Date: 1/19/2017

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev. A 12/08/09 New Issue DL
12/11/08 Doc Release DL
Update 13/07/09 DL ver: DD
13/12/09 DL
Ipp Rev. E Dwg Update 14/01/09 DL
Dwg. Update 15/01/27 DL

IPP Rev B
IPP Rev. C Dwg.
IPP Rev D Dwg Update
IPP Rev. F

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4635-144 *D4635-144* Aft Ceiling Replacement Panel Assembly, RH		Manufactured	No			100	Each	0.0000	1	1			
									**			B/154721	Smb
D4646-1 *D4646-1* Plenum Cap Assembly		Manufactured	No			100	Each	23.0000	1	1			
									**			154711	Smb
					<u>Location</u>	<u>Loc Qty</u>							
					MF009	23							
					125003	11							
					152626	12							
D4652-5 *D4652-5* Air Valve, 1.25 Id Disk Type		Manufactured	No			100	Each	0.0000	1	1			
									**			B/138691	Smb
D4655-1 *D4655-1* Speaker		Manufactured	No			100	Each	17.0000	1	1			
									**				
					<u>Location</u>	<u>Loc Qty</u>							
					MF002	17							
					117634	17							

DAS
6
8-89

JAN 13 2017

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QS1042) Approval	
Description Work Order Deviation		Disposition			
				Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER : ☐					

Picklist Print

Monday, December 19, 2016 4:00:14 PM

Work Order ID: 154706

154706

Parent Item: D4635-044

D4635-044

Parent Item Name: Aft Ceiling Panel Assembly, RH

Start Date: 1/6/2017

Required Date: 1/19/2017

Start Qty: 1.00

Required Qty: 1.00

D4708-9 Manufactured No

100 Each 14.0000 1 1

D4708-9

Lanyard

**

DAS
6

JAN 13 2017

Location

Loc Qty

Loc Code

MF004

14

150077

14

D4728-046 Manufactured No

100 Each 15.0000 1 1

D4728-046

RH Cabin Speaker #3

**

DAS
6

JAN 13 2017

Location

Loc Qty

Loc Code

MF002

5

124239

5

MF009

10

124239

10

D4743-1 Manufactured No

100 Each 20.0000 1 1

D4743-1

Speaker Grill

**

DAS
6

JAN 13 2017

Location

Loc Qty

Loc Code

MF005

20

149065

20

MS21044-N08 Purchased No

100 Each 34.0000 4 4

MS21044-N08

Nut

**

DAS
6

JAN 13 2017

Location

Loc Qty

Loc Code

ST302

34

m131452

34

134502

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date : _____	Step #: _____	QTY Effective : _____		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Mislabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					

Picklist Print

Monday, December 19, 2016 4:00:15 PM

Work Order ID: 154706

154706

Parent Item: D4635-044

D4635-044

Parent Item Name: Aft Ceiling Panel Assembly, RH

Start Date: 1/6/2017

Required Date: 1/19/2017

Start Qty: 1.00

Required Qty: 1.00

MS21919-WDG8 Purchased

No

100

Each

21.0000

3

3

MS21919-WDG8

Clamp

Location

Loc Qty

Loc Code

ST293

21

m135408

21

100

Each

421.0000

4

4

MS24693-BB51

Purchased

No

MS24693-BB51

Screw

Location

Loc Qty

Loc Code

ST288

421

m128057

421

100

Each

1,682.000

4

4

NAS1149DN832J

Purchased

No

NAS1149DN832.J

Washer

Location

Loc Qty

Loc Code

ST264

1682

M135297

1682

DAS
9-86

JAN 12 2017

136582 Y2

DAS
9-86

JAN 12 2017

4

DAS
9-86

JAN 12 2017

4

DQA: _____ Date: _____




WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐		AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐					
Date :		Step #:		QTY Effective :				MRB (QS1042) Approval 	
Description Work Order Deviation				Disposition					
								Completed By	
								Lead hand / Supervisor Approval Verification	
								QC / QA Coordinator Approval	

Root Cause			FAULT CATEGORY							
Environment	☐	No Re-verification	☐	Pressure/Forced	☐	Temperature/Cure	☐	Power Loss/Surge	☐	Positioned Wrong
Design	☐	Operator	☐	Bending	☐	Set-up	☐	Folio/Program	☐	Outside Dimensions
Doc/Data	☐	Offset/Setup	☐	Centre Not Concentric	☐	BOM/Route	☐	Grain	☐	Over/Under tolerance
Equip/Tooling	☐	Supplier	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Part Incorrect
Handling/Pre	☐	Training	☐	Crimp/Kink/Ripple/Wave	☐	Inspection Incomplete/Unqualified	☐	Wrong Stock Pulled	☐	Part Lost/Missing
Material	☐	Use for Testing	☐	Cuffs	☐	Contamination	☐	Out of Sequence	☐	Part Moved
Internal Transport	☐	Poor Information	☐	Crushing	☐	Countersink	☐	Off-set	☐	Drawing
Tribal Knowledge	☐	Rushing	☐	Heat Treat	☐	Cut Too Short	☐	Mislabeled	☐	Finish
LOA	☐	Product Improvement	☐	Wave/Twist in Tube	☐	Instructions Incomplete/Unclear	☐	Fit/Function	☐	Misread
Substation	☐	Process Improvement	☐	Marks/Chatter	☐	Drill Holes	☐	Misaligned/off center	☐	Turning Sequence
Past Expiry Date	☐	Manufacturing Process	☐	OTHER :						
Misidentified	☐	Past Due	☐							



D4635-044 RH, AFT CEILING PANEL ASSY

NOTES:

- 1) MATERIAL: N/A
- 2) FINISH: N/A
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: IDENTIFY PER QSI 044 6.4, ON SMOOTH SIDE
- 7) WEIGHT: 5.0 lbs
- 8) INSTALL D4728-046 WIRE HARNESS PER QSI 048
- 9) ON D4708-9 LANYARD OPEN TO $\phi 0.196$ BOTH ENDS

ITEM	QTY -044	P/N	DESCRIPTION
1	X	D4635-044	RH, AFT CEILING PANEL ASSY
2	1	D4635-144	RH, AFT CEILING REPLACEMENT PANEL ASSY
3	1	D4646-1	PLENUM CAP ASSEMBLY
4	1	D4652-3 (REF)	MOUNTING NUT (PART OF D4652-5)
5	1	D4652-5	AIR VALVE, 1.16 ID DISK TYPE
6	1	D4655-1	SPEAKER
7	1	D4708-9	LANYARD
8	1	D4728-046	RH SPEAKER #3 HARNESS ASSY
9	1	D4743-1	SPEAKER GRILL
10	4	MS21044-N08	NUT, SELF-LOCKING
11	3	MS21919WDG8	CLAMP
12	4	MS24693-BB51	SCREW, CSK 100°
13	4	NAS1149DN832J	WASHER

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER

NO. 154706 MJ
16-12-20



RELEASED

2015 JAN 26 up

APPROVED

DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	RF		
CHECKED	AK	DRAWING NO.	REV. F
MFG. APPR.	DL	D4635	SHEET 7 OF 18
APPROVED	HS	TITLE	SCALE
DE APPR.	DS	OUTBOARD CEILING PANELS	NTS
DATE	14.11.28	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD	

8 7 6 5 4 3 2 1



D4635-044 RH, AFT CEILING PANEL ASSY
AUXILIARY VIEW

RELEASED
2015 JAN 26 *qr*

APPROVED	DESIGN	RF	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
	DRAWN	RF		
	CHECKED	AK	DRAWING NO.	REV. F
	MFG. APPR.	DL	D4635	SHEET 8 OF 18
	APPROVED	HS	TITLE	SCALE
	DE APPR.	DS	OUTBOARD CEILING PANELS	NTS
	DATE	14.11.28	COPYRIGHT © 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD	

8 7 6 5 4 3 2 1

Daryl Leger

From: David Shepherd
Sent: Thursday, May 14, 2015 12:35 PM
To: Nigel Forbes; Bill Beckett
Cc: Roberto Fuentes; Linda Lacelle; Mario Poulin; Daryl Leger; Harvey Siemens
Subject: RE: 139 Ceilings Deviation

Nigel,

Thanks for the clarification. I have a much better understanding of what happened here. My assumption had been that we were holding off ordering parts until the newer, cheaper parts were approved so that we could reduce our costs. There is certainly no Engineering objection to using the existing stock.

On the lights, the part number did not change (still D4638-1) even though the supplier did, so this is not a deviation. Both the Bruce p/n and Emteq p/n are acceptable.

On the vents, the part number changed from D4652-1 to D4652-5 because the appearance of the part was quite different, so all drawings now call up D4652-5. Suggest we get Roberto to issue a DEO that allows the D4652-1 to be used in place of D4652-5 until stock is depleted.

In both cases, we should set aside a portion of the old stock to support customers who already have the kits. Maybe 10 of the lights and 30 of the vents, or something like that.

Regards,
David

From: Nigel Forbes
Sent: May-14-15 8:31 AM
To: David Shepherd; Bill Beckett
Cc: Roberto Fuentes; Linda Lacelle; Mario Poulin; Daryl Leger; Harvey Siemens
Subject: RE: 139 Ceilings Deviation

David,

Apologies for the delay in replying. After reviewing the history on these items, here's the background:

- The lights, long lead time (90+ days) and minimum quantities to get them at \$765 a piece. Plus, these had to be shipped to Mr. Rowe to incorporate in the harnesses and that added to the lead time. So again, we placed blanket P.O based on forecast and we ended up with the these quantities and we can't return them. See below.

From: Shonda Wallace/ATL/Satair <sow@satair.com>
Date: May 14, 2015 at 10:09:59 AM EDT
To: Linda Lacelle <llacelle@dartaero.com>
Subject: RE: BR9741-401-001

Linda,

Unfortunately we do not buy parts back.

Best regards,

Shonda Wallace
Customer Order Specialist

Tel: +1 404 675 6328